J GH 47-94 61-02-PM

وعورو يوس فعيد

HAZARD

## MATERIAL SAFETY DATA SHEET

Rose Art Industries, Inc. 6 Regent Street Livingston NJ 07039

Rose Art Industries, Inc. Emergency Tel: (973)-535-1313

Fax: (973)-533-9447 Date Issued: January 29, 2002

MSDS No: 0161

SECTION I - PRODUCT IDENTIFICATION

Product Name: # 2204 Rose Art School Glue

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

COMPONENT CAS #

NONE

SECTION III - PHYSICAL DATA

Boiling Point: N/A Vapor Pressure (mm Hg.): N/A

Vapor Density: (Air = 1): N/A Solubility in H2O: SOLUBLE

Specific Gravity  $(H_2O = 1)$ : 1.06 Evaporation Rate: N/A

Appearance and Odor: White Liquid, odor characteristic

SECTION IV - REACTIVITY DATA

Unstable: Conditions to Avoid:

Stable: X

Incompatibility (Materials to Avoid): N/A

Hazardous Decomposition or Byproduct: N/A

May Occur:

Hazardous

Polymerization

Will Not Occur: X

Conditions to Avoid: None

SECTION V - FIRE AND EXPLOSION HAZARD DATA

Plash Point: NOT COMBUSTIBLE

Plammable Limits: N/A

M5DS #161 page 2

sent sent to principle of

Fire Extinguishing Media: Use water fog foam or dry chemical

Special Fire Fighting Procedure: Use of self-contained breathing apparatus.

Unusual Explosion and Fire Hazard: N/A

## SECTION VI - HEALTH HAZARD DATA

Route(s) of Entry:

Inhalation? POSSIBLE Skin? POSSIBLE Ingestion? POSSIBLE

Health Hazards (Acute and Chronic) PRODUCT IS NON-TOXIC

Carcinogenicity: NTP? NO IARC Monographs? NO OSHA Regulated? NO Signs and Symptoms of Exposure: NONE KNOWN

Medical Conditions
Generally Aggravated by Exposure: NONE KNOWN

Bmergency and First Aid Procedure: IF LARGE QUANTITIES IS INGESTED OR IF GLUE GETS INTO THE EYES, FLUSH WITH WATER AND CONTACT PHYSICIAN BOTH CASES.

## SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to Be Taken in Case Material is Released or Spilled: IF NOT COMPLETELY DRIED USE A WARM, DAMP CLOTH. IF GLUE IS DRIED USE SOAP AND WATER.

Waste Disposal Method: ABIDE LOCAL, STATE, AND FEDERAL REGULATIONS FOR NON-TOXIC WASTE.

Precautions to Be Taken in Handling and Storing: STORE IN DRY AND COOL PLACE

Other Precautions: AVOID CONTACT WITH SKIN, EYES. PACE AND HARI. MAY CAUSE BONDING TO DIRECT SKIN BEFORE DRYING. ALSO, AVOID CONTACT WITH FABRIC BASED FURNITURE, CARPETING, ETC.

06/19/2006 09:51 9/3033344 3n-43-04 01:53PM

MSDS #161. page 3

SECTION VIII - CONTROL MEASURES

Respiratory Protection (Specify Type): NONE

Ventilation: NONE

Protective Gloves: N/A Eye Protection: N/A

Other Protective Clothing or Equipment: N/A

Work/Hygienic Practices: W/A